

Oil Field Environmental Incident Summary

Incident: 20150123171650 **Date/Time of Notice:** 01/23/2015 17:16

Responsible Party: SLAWSON EXPLORATION COMPANY, INC.

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: VAN HOOK 1-9 SWD

Field Name: SANISH

Well File #: 90143

Date Incident: 1/23/2015

Time Incident: 06:30

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 91

Sec: 9

Qtr: NW NE

Location Description:

Submitted By: Ray Gorka

Received By:

Contact Person: Ray Gorka
1675 BROADWAY STE 1600
DENVER, CO 80202

General Land Use: Cultivated

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 4300 Feet

Distance Nearest Water Well: 4300 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels	15	Barrels	15	barrels
Brine						
Other			5	Barrels	5	barrels

Description of Other Released Contaminant:

Fresh water/snow melt

Inspected:

Written Report Received: 5/31/2016

Clean Up Concluded: 1/23/2015

Risk Evaluation:

none

Areal Extent:

.....

Potential Environmental Impacts:

none, ground frozen and liquids vacuumed up.

Action Taken or Planned:

Firing the driver.....

Wastes Disposal Location: Licensed disposal facility.

Agencies Involved:

Updates

Date: 1/25/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.